


Siltronic RI/FS Planning Schedule

Task Name	Start Date	End Date	2006					2007		
			Aug	Sep	Oct	Nov	Dec	Jan	Feb	Mar
RI Scoping Document	8/15/2006	3/2/2007								
Scoping Document Develop and Submit	8/15/2006	11/17/2006								
DEQ Review and Comment	11/20/2006	12/20/2006								
Revise Scoping Document	12/21/2006	1/31/2007								
DEQ Review and Approval	2/1/2007	3/1/2007								
DEQ Approval	3/2/2007	3/2/2007								
RI and Source Control Work Plan	TBD	TBD								
Develop and Submit Work Plan	TBD	TBD								
DEQ Review and Comment	TBD	TBD								
Revise Work Plan	TBD	TBD								
DEQ Review and Approval	TBD	TBD								
DEQ Approval	TBD	TBD								
RI/RA/Source Investigations	TBD	TBD								
Sampling and Analysis	TBD	TBD								
RI Report, Source Screen Report, and Level 2 RA	TBD	TBD								
DEQ Review and Comment	TBD	TBD								
Revise RI Report	TBD	TBD								
DEQ Review and Approval	TBD	TBD								
DEQ Approval	TBD	TBD								
Level 3 RA (if needed)	TBD	TBD								
DEQ Review and Comment Level 3 RA (if needed)	TBD	TBD								
Revise Level 3 RA (if needed)	TBD	TBD								
DEQ Review and Approval Level 3 RA (if needed)	TBD	TBD								
DEQ Approval	TBD	TBD								
FS for Upland Remediation and Source Controls	TBD	TBD								
FS/Source Control Investigations (as necessary)	TBD	TBD								
Draft FS/Source Control Plan	TBD	TBD								
DEQ Review and Comment	TBD	TBD								
Revise FS and Plan	TBD	TBD								
DEQ Review and Approval	TBD	TBD								
DEQ Approval	TBD	TBD								

Task 

Milestone 

TBD = To be determined